



Attorney Docket No. 122.1581

cc/c

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Makoto ONOZAWA, et al.

Application No.: 10/776,286

ATTENTION

Confirmation No.: 3508

CERTIFICATE OF CORRECTION

Filed: February 12, 2004

BRANCH

U.S. Patent No.: 7,084,839

Batch No.:

Issued: August 1, 2006

For: PRE-DRIVE CIRCUIT, CAPACITIVE LOAD DRIVE CIRCUIT AND PLASMA DISPLAY APPARATUS

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: Nov. 8, 2006

By: *H. J. Staas*
H. J. Staas
Registration No. 22,010

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

Certificate
NOV 13 2006
of Correction

NOV 13 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 7,084,839

DATED : August 1, 2006

INVENTOR(S) : Makoto ONOZAWA, et al.

Column 17, Line 3, after " voltage," change "a" to --is--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 7,084,839

No. of add'l copies
@ 50¢ per page

⇒

NOV 13 2006